



MAKEPaints

MAKEYD ZP PRIMER 201 Alkyd A/C Primer

PRODUCT DESCRIPTION	Modified Zinc Phosphate alkyd primer.																								
RECOMMENDED USE	Multipurpose primer for new construction or maintenance, suitable for use on exterior and interior steel in moderately corrosive marine and industrial atmosphere.																								
CHARACTERISTIC	<ul style="list-style-type: none"> • Lead and chromate free. • To be recoated with conventional paint system. • Good Adhesion properties. • Fast drying. 																								
PHYSICAL DATA	<ul style="list-style-type: none"> • Colour : Grey, Oxide Red • Gloss level : Flat • Specific Gravity : 1.3 ± 0.5 kg/ltr • Volume Solid : Approx. 47± 2 % • Dry Film Thickness : 35 microns per coats • Theoretical Coverage : 13.4 sq.m/ltr for 35 microns • Drying Time : <table border="1"> <thead> <tr> <th>Temperature</th> <th>Touch Dry</th> <th>Hard Dry</th> </tr> </thead> <tbody> <tr> <td>26°C</td> <td>60 minutes</td> <td>12 hours</td> </tr> <tr> <td>32°C</td> <td>45 minutes</td> <td>11 hours</td> </tr> <tr> <td>36°C</td> <td>30 minutes</td> <td>10 hours</td> </tr> <tr> <td>40°C</td> <td>20 minutes</td> <td>9 hours</td> </tr> </tbody> </table> <ul style="list-style-type: none"> • Full Cure : - • Painting Interval : Min : 3 Hours, Max Unlimited. • VOC : Max. 389 g/litre. • Flash Point(DIN 53213) : 39°. • Pot Life : - • Service Temperature : Continuous : 60°C ; Periodic : up to 90°C. • Shelf Life : 12 months (cool and dry place) 	Temperature	Touch Dry	Hard Dry	26°C	60 minutes	12 hours	32°C	45 minutes	11 hours	36°C	30 minutes	10 hours	40°C	20 minutes	9 hours									
Temperature	Touch Dry	Hard Dry																							
26°C	60 minutes	12 hours																							
32°C	45 minutes	11 hours																							
36°C	30 minutes	10 hours																							
40°C	20 minutes	9 hours																							
SURFACE PREPARATION	Steel : blast cleaned in situ to at least SSPC – SP10 and free from rust, scale, shop primer and any other contamination.																								
CONDITION OF APPLICATION	<p>Temperature ; minimum 10°C : maximum 50°C.</p> <p>Relative Humidity maximum 85%.</p> <p>Substrate temperature should be at last 3°C above dew point.</p>																								
INSTRUCTION FOR USE	Stir well before use, preferable by mechanical mixer to ensure good homogeneity.																								
APPLICATION DETAILS	<table border="1"> <thead> <tr> <th>Method Application</th> <th>Airless Spray</th> <th>Air Spray</th> <th>Roller Brush</th> </tr> </thead> <tbody> <tr> <td>Thinner No</td> <td>MAKE 902</td> <td>MAKE 902</td> <td>MAKE 902</td> </tr> <tr> <td>Volume of Thinner</td> <td>Max 10%</td> <td>Max 15%</td> <td>Max 5%</td> </tr> <tr> <td>Nozzle orifice</td> <td>0.017 (0.43m)</td> <td>2 mm</td> <td>-</td> </tr> <tr> <td>Nozzle Pressure</td> <td>150 bar (2100 psi)</td> <td>4 bar / 57 psi</td> <td>-</td> </tr> <tr> <td>Cleaning Solven</td> <td>MAKE 10</td> <td>-</td> <td>-</td> </tr> </tbody> </table>	Method Application	Airless Spray	Air Spray	Roller Brush	Thinner No	MAKE 902	MAKE 902	MAKE 902	Volume of Thinner	Max 10%	Max 15%	Max 5%	Nozzle orifice	0.017 (0.43m)	2 mm	-	Nozzle Pressure	150 bar (2100 psi)	4 bar / 57 psi	-	Cleaning Solven	MAKE 10	-	-
Method Application	Airless Spray	Air Spray	Roller Brush																						
Thinner No	MAKE 902	MAKE 902	MAKE 902																						
Volume of Thinner	Max 10%	Max 15%	Max 5%																						
Nozzle orifice	0.017 (0.43m)	2 mm	-																						
Nozzle Pressure	150 bar (2100 psi)	4 bar / 57 psi	-																						
Cleaning Solven	MAKE 10	-	-																						
STORAGE & HANDLING	The product must be stored in accordance with national regulation. Storage conditions are to keep the containers in a dry, cool, well ventilated space and away from source of heat and ignition. Containers must be kept tightly closed. Handle with care, stir well before use.																								

SAFETY PRECAUTION

Keep away from heat, spark and open flames. Avoid breathing of vapour on skin and eye contact. Keep container closed and store in cool, ventilated area when not in use. Proper ventilation and protective measures must be provided during mixing, application and drying, to keep vapour concentration within safe limits and to protect against toxic hazard. Necessary safety equipment must be used and ventilation requirements carefully observed, especially in confined or enclosed spaces, such as tank interior and building.

DISCLAIMER

The information in this product data sheet is given to the best of our knowledge based on laboratory testing and practical experience. If the product is used under condition beyond our control, we cannot guarantee anything but the quality of the products it self. The information in this product data sheet is liable for modification from time to time in the light of experience and our policy of continuous product development, and without further notice.